

**DAEWOO DH50 DIGGER (ST23469)** 

£3,250



## PRODUCT DESCRIPTION

Daewoo DH50 Digger (ST23469)

Hour clock not working

Complete with 3 buckets

Steel tracks - chains are worn out

No front windows

Starts, runs, drives, digs - that's about it!

Offset boom welded up - now fixed boom

Horrible thing!

£3,250 + VAT